From:	Flock Safety Support
To:	Stephen Best
Cc:	brendon.norton@flocksafety.com; libby.landers@flocksafety.com; Eligio Lara; Daniel Cohen; Stephen Best; jake.sherman@flocksafety.com; Michael Balcorta
Subject:	RE: Flock Cameras Still Failing to read...mostly night images... specifically Cameras 086 and 116
Date:	Thursday, May 16, 2024 7:17:56 AM

*** EXTERNAL EMAIL: Please use caution when opening links or attachments.***

Good Morning Corporal,

Thanks for taking the time to put this together for us.

As mentioned, camera 086 SB Bradley (north of Hancock) is scheduled to be replaced on 5/24. After this visit, I'd like to closely monitor the results. If we're still seeing a low % of plate reads, we may need to discuss an alternate location. It will likely be easier to hop on a call with you if it comes to that.

I'll have the camera engineering team evaluate 116 WB Betteravia (east of Broadway-Lane 1 and 2). Would you mind sending me at least one image card from search of your vehicle? You'll need to open the search to the time you pass the camera, opt into the All Images filter, and then click the + button on the image card of your vehicle.

The Lookup tool results are helpful but I need to provide examples of when we made the mistake.

I hope to hear from you soon.

Stay safe,
Alex C

---------- Original Message ----------
From: Stephen Best [sbest@cityofsantamaria.org]
Sent: 5/16/2024, 9:57 AM
To: libby.landers@flocksafety.com; support@flocksafety.com; jake.sherman@flocksafety.com; brendon.norton@flocksafety.com
Cc: elara@cityofsantamaria.org; dcohen@cityofsantamaria.org; sbest@cityofsantamaria.org; mbalcorta@cityofsantamaria.org
Subject: Flock Cameras Still Failing to read...mostly night images... specifically Cameras 086 and 116

Flock Support,
I have been reporting Camera “086 SB Bradley (north of Hancock)” as frequently failing to read my plate since May of 2022 and Camera “116 WB Betteravia (east of Broadway Lane 1 and 2)” since August of 2023.

(And these are only the cameras I happen to be testing because I pass by them every morning).

You have made adjustments to the cameras and changed equipment but the Flock cameras are

still only recording my plate in the mornings about 2% of the time. Very poor percentage.

(I just received an email from Flock Safety saying Camera 086 is going to be replaced, again, on 05-24-24, so that one is already scheduled to be workedon. FYI)

Last 30 days:

I passed Camera 086 between 0530-0600 Hrs. 17 times. It read my plate 1 time. .05% success rate.

I passed Camera 116 between 0530-0600 Hrs. 17 times. It read my plate 4 times. 2% success rate.

(See attached Look Up results)

Corporal Stephen L. Best

Santa Maria Police Department

1111 W. Betteravia Rd., Santa Maria, CA 93455

(805)928-3781 X2491

sbest@ci.santa-maria.ca.us

sbest@cityofsantamaria.org

WARNING! The information contained in this transmission is privileged and confidential. It is intended only for the use of the person(s) named above. If you are not the intended recipient, you are hereby notified that any review, dissemination, distribution or duplication of this communication is strictly prohibited. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message and any attachments.

To unsubscribe from this group and stop receiving emails from it, send an email to support+unsubscribe@flocksafety.com.

thread::Kf0bwelhLu-pItbeQyLypQ4::